

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. 037120

Water Right Permit No. _____

(1) OWNER: Name B. Williamson Address 5017 S. Bayview Rd Langley WA.

(2) LOCATION OF WELL: County ISLAND NW 1/4 NW 1/4 Sec 4 T. 29 N. R. 3E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) 5017 Bayview Rd Langley 98260

(3) PROPOSED USE: ☒ Domestic ☐ Irrigation ☐ DeWater ☐ Industrial ☐ Test Well ☐ Municipal ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one) 1
Abandoned ☐ New well ☒ Deepened ☐ Reconditioned ☐ Method: Dug ☐ Cable ☒ Rotary ☐ Bored ☐ Driven ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 182 feet. Depth of completed well 182 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6 " Diam. from 0 ft. to 177 ft.
Welded ☒ " Diam. from _____ ft. to _____ ft.
Liner installed ☐ " Diam. from _____ ft. to _____ ft.
Threaded ☐ " Diam. from _____ ft. to _____ ft.

Perforations: Yes ☐ No ☒

Type of perforator used _____

SIZE of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐

Manufacturer's Name Cook

Type STAINLESS

Model No. _____

Diam. 6 Slot size 12 from 177 ft. to 182 ft.

Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel _____

Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.

Material used in seal BENTONITE

Did any strata contain unusable water? Yes ☐ No ☒

Type of water? _____ Depth of strata _____

Method of sealing strata off _____

(7) PUMP: Manufacturer's Name STARITE

Type: Sub H.P. _____

(8) WATER LEVELS: Land-surface elevation above mean sea level 150+ ft.

Static level 152 ft. below top of well Date Jul 90

Artesian pressure _____ lbs. per square inch Date _____

Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level

Was a pump test made? Yes ☐ No ☒ If yes, by whom? _____

Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs.

" " " " " "

" " " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time Water Level Time Water Level Time Water Level

Date of test _____

Bailer test 15 gal./min. with 12 ft. drawdown after 4 hrs.

Airtest _____ gal./min. with stem set at _____ ft. for _____ hrs.

Artesian flow _____ g.p.m. Date _____

Temperature of water _____ Was a chemical analysis made? Yes ☐ No ☒

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
SANDY	0	18
SANDY CLAY	18	51
CLAY	51	70
SANDY CLAY	70	146
DIRTY SAND	146	164
WATER SAND	164	182
CLAY CHUNKS	182	

RECEIVED

JUL 30 1990

DEPT. OF ECOLOGY

Work started July 28, 1990 Completed July 27, 1990

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME WHIDBEY DRILLERS
(PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address PAK HARBOR WA.

(Signed) Penelope Jolan License No. 129
(WELL DRILLER)

Contractor's Registration No. WA10289 MM Date Jul 27, 1990

(USE ADDITIONAL SHEETS IF NECESSARY)

WATER WELL REPORT

STATE OF WASHINGTON

29/3E/5 K
Start Card No. 037120

Water Right Permit No. _____

(1) OWNER: Name WYNTER CREEK WATER ASSN. Address _____

(2) LOCATION OF WELL: County ISLAND NW 4 SE 45 T. 29 N. R. 3E W.M.

(2a) STREET ADDRESS OF WELL (or nearest address) Bayview Rd 98260

(3) PROPOSED USE: ☒ Domestic ☐ Industrial ☐ Municipal ☐
☐ Irrigation ☐ Test Well ☐ Other ☐
☐ DeWater

(4) TYPE OF WORK: Owner's number of well (if more than one) 2

Abandoned ☐ New well ☒ Method: Dug ☐ Bored ☐
Deepened ☐ Cable ☒ Driven ☐
Reconditioned ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6 inches.
Drilled 182 feet. Depth of completed well 182 ft.

(6) CONSTRUCTION DETAILS:

Casing installed: 6 Diam. from 0 ft. to 177 ft.
Welded ☒ Diam. from _____ ft. to _____ ft.
Liner installed ☐ _____ ft. to _____ ft.
Threaded ☐ _____ ft. to _____ ft.

Perforations: Yes ☐ No ☒
Type of perforator used _____
Size of perforations _____ in. by _____ in.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.
_____ perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐
Manufacturer's Name COOK
Type STAINLESS Model No. _____
Diam. 6 Slot size 12 from 177 ft. to 182 ft.
Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel _____
Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.
Material used in seal BENTONITE
Did any strata contain unusable water? Yes ☐ No ☒
Type of water? _____ Depth of strata _____
Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
Type: SUB H.P. _____

(8) WATER LEVELS: Land-surface elevation 150.4 ft.
Static level 152 ft. below top of well Date Jul 90
Artesian pressure _____ lbs. per square inch Date _____
Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☒ No ☐ If yes, by whom? _____
Yield _____ gal./min. with _____ ft. drawdown after _____ hrs.

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level
------	-------------	------	-------------	------	-------------

Date of test _____

Bailer test 15 gal./min. with 12 ft. drawdown after 4 hrs.

Airtest _____ gal./min. with stem set at _____ ft. for _____ hrs.

Artesian flow _____ g.p.m. Date _____

Temperature of water _____ Was a chemical analysis made? Yes ☒ No ☐

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
SANDY	0	18
SANDY CLAY	18	51
CLAY	51	70
DRY SANDY CLAY	70	146
DRY SAND	146	164
WATER IN SAND	164	182
CLAY CHUNKS	182	

RECEIVED

JUL 01 1991

DEPT. OF ECOLOGY

(ISLAND COUNTY)
WELL SITE APPROVED

Work started July 23 19. Completed July 1990

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME WHIDBEY DRILLERS
(PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address OAK HARBOR WA 98271

(Signed) Robert John License No. 129
(WELL DRILLER)

Contractor's Registration No. WA#B289MM Date JUNE 1991

(USE ADDITIONAL SHEETS IF NECESSARY)